

FIG. 1a






FIG. 1b

10/018060

2/14












4/14

B4 —	C4 —	$t_c = 0$	$\swarrow 7$	$t_b = 0$	B3 = 0
B3 —	C3 —	0.35			
B2 —	C2 —	0.70		0.55	B2
B1 —	C1 —	1.05		1.05	B1

C5	$t_c = 0$	$\swarrow 7$	$t_b = 0$	B4 = 0
C4	0.3		0.4	B3 → C3, C2, C1
C3	0.6			
C2	0.9		0.8	B2 → C2, C1
C1	1.2		1.2	B1 → C1

FIG. 3






FIG. 7a




FIG. 7b








FIG. 7c



6/14



7/14



8/14



9/14




FIG. 10




FIG. 11a







FIG. 11b

10/14



11/14




FIG. 14

107018060

12/14




FIG. 15

13/14




FIG.16




FIG. 17

10/018060

14/14




FIG. 18

	H	G	Vi	
HS	H1	G1	Cod 2, Cod 3 BC, KF / KS, 23	aut
	H1/2	G1/2	23, Cod 2	
	H2	G2	Cod 1	

FIG. 19